


FINE spol. s r.o. Závěrka 12, Praha 6, 169 00		<b>Dilatometer test (DMT)</b>		<b>DMT1</b>
Project: <b>Apartment building "Moonlighting" - Geological survey</b>				
Project ID: AA_0014 - 2019	Annex no.: 21/c7.	Overall depth: 14,00 m		
Location: New street 22/ Liberec		Acc. to standard: EN ISO 22476-11		
Measured: Bill Fieldman	Coordinate X: 1039757,12	Calibration		$\Delta A_{ini}$ : 11,00 kPa
Evaluated: Joe Freeman	Coordinate Y: 745165,25	pressure:		$\Delta B_{ini}$ : 24,00 kPa
Date of test: 11.10.2016	Coordinate Z: 209,27 m			$\Delta A_{end}$ : 18,00 kPa
Scale: one page	GWT: 5,00 m			$\Delta B_{end}$ : 64,00 kPa



**Notes:**

- Cloudy/ Windy / 21°C
- Raw data not modified
- Equipment checked and in accordance with EN ISO 22476-11